

關閉PDF預覽

北緯 25°33'18.6" ，東經 121°24'57.0" 。
 北緯 25°36'13.8" ，東經 121°31'09.0" 。
 北緯 25°41'09.0" ，東經 121°39'20.4" 。
 北緯 25°38'32.4" ，東經 121°41'35.4" 。
 北緯 25°33'53.4" ，東經 121°33'43.8" 。
 北緯 25°30'39.0" ，東經 121°27'01.8" 。
 北緯 25°20'13.8" ，東經 121°27'25.2" 。
 北緯 25°38'12.6" ，東經 121°32'49.8" 。
 北緯 25°40'33.6" ，東經 121°31'22.8" 。
 北緯 25°48'18.0" ，東經 121°46'23.4" 。
 北緯 25°54'58.8" ，東經 122°04'01.2" 。
 北緯 25°52'18.6" ，東經 122°05'32.4" 。
 北緯 25°48'31.2" ，東經 121°56'33.6" 。 *WGS84

交通部航港局局長
 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

November 2, 2023

APCN2 (Asia Pacific Cable Network-2) Submarine Cable 、 TPE (Trans Pacific Express) Submarine Cable System Repair

Source
 Details

Taiwan Ministry of Interior Letter No. 1120141152 dated November 2, 2023

Submarine cable system : APCN2 (Asia Pacific Cable Network-2)

Segment: S6 (Tanshui-Chikura)

Fault date/time: 13-Oct-2023 at approx. 14:31 UTC

Schedule: 28-Nov-2023 to 20-Dec-2023

Water depth: 80 meters

Submarine cable system : TPE (Trans Pacific Express)

Segment: S4 (Tanshui-Chongming)

Fault date/time: 19-Sep-2023 at approx. 21:58 UTC

Schedule: 28-Nov-2023 to 20-Dec-2023

Water depth: 120meters

Positions

Lat. 25°20'22.8" N., Long. 121°23'41.4" E.

Lat. 25°30'27.6" N., Long. 121°23'28.2" E.

Lat. 25°33'18.6" N., Long. 121°24'57.0" E.

Lat. 25°36'13.8" N., Long. 121°31'09.0" E.

Lat. 25°41'09.0" N., Long. 121°39'20.4" E.

Lat. 25°38'32.4" N., Long. 121°41'35.4" E.

Lat. 25°33'53.4" N., Long. 121°33'43.8" E.

Lat. 25°30'39.0" N., Long. 121°27'01.8" E.

Lat. 25°20'13.8" N., Long. 121°27'25.2" E.

Lat. 25°38'12.6" N., Long. 121°32'49.8" E.

Lat. 25°40'33.6" N., Long. 121°31'22.8" E.