



交通部航港局航船布告

中華民國 114 年 9 月 10 日

515

礙航公告(南區)全球光網電訊股份有限公司之C2C海纜系統
(C2C)區段1在臺灣東沙島西北方附近海域發生海纜故障於民國
114年09月25日至114年10月20日派遣『彼德輝柏號(PETER
FABER)海纜船』與『伊勒代克斯號(ILE D' AIX)海纜船』進行
作業

依 據 全球光網電訊股份有限公司 114 年 9 月 9 日全網 114 字第 043 號函
說 明 航行船隻請注意瞭望並避讓，以維航行安全。
位 置 北緯 21°17'19.7"，東經 116°03'40.6"。
北緯 21°19'20.6"，東經 116°05'36.8"。
北緯 21°15'27.6"，東經 116°09'50.1"。
北緯 21°13'36.8"，東經 116°07'43.0"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

September 10, 2025

515

Taiwan Southwestern Waters - Cable Repair Operation

Source

TELSTRA SERVICES (TAIWAN) INC. , letter No.114043 dated September 09, 2025.

Details

Cable Repair Operation will be undertaken on September 25 to October 20, 2025.
All vessels are prohibited from sailing the survey waters.

Positions

Lat. 21°17'19.7" N., Long. 116°03'40.6" E.
Lat. 21°19'20.6" N., Long. 116°05'36.8" E.
Lat. 21°15'27.6" N., Long. 116°09'50.1" E.
Lat. 21°13'36.8" N., Long. 116°07'43.0" E. *WGS84

*Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung*