



交通部航港局航船布告

中華民國 115 年 4 月 30 日

236

礙航公告(中區)海洋竹南離岸風力發電場「離岸風機航路標誌設施故障」

依據 海洋風力發電股份有限公司 115 年 4 月 28 日洋 T06 字第 1150400024 號函
說明 一、旨述經海洋風力發電股份有限公司檢修，已完成部分航路標誌設施之修繕作業，惟尚有部分設施持續辦理修繕中。該公司將持續掌握相關設備狀況，並於天氣條件允許下儘速安排出海作業，預計於 115 年 10 月 30 日前完成全部修繕，惟仍視天候狀況而定；待修繕完畢後，將另行通知。

位置 二、航經該水域船隻請多加注意。
北緯 24°43'49.6"，東經 120°49'29.4"。
北緯 24°42'45.9"，東經 120°50'05.5"。
北緯 24°43'12.0"，東經 120°48'46.9"。
北緯 24°41'58.2"，東經 120°49'35.9"。
北緯 24°41'35.8"，東經 120°49'01.5"。
北緯 24°41'27.6"，東經 120°48'24.1"。*WGS84
備註 更新編號第20260043號布告

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

April 30, 2026

236 Taiwan Offshore-FOWI Formosa 1 Offshore Wind Farm wind turbine navigation aid(AtoN) failure.

Source Formosa 1 Offshore Wind Farm, letter No. 1150400024 dated 28th April, 2026.
Details The subject facilities have undergone maintenance by Formosa 1 Offshore Wind Farm, and repair works for part of the aids to navigation have been completed. However, some facilities are still under repair. Formosa 1 Offshore Wind Farm will continue to monitor the condition of the relevant equipment and arrange offshore operations as soon as weather conditions permit. All repair works are expected to be completed by 30 October 2026, subject to weather conditions. A further notice will be issued upon completion.
Positions Lat. 24°43'49.6" N., Long. 120°49'29.4" E.
Lat. 24°42'45.9" N., Long. 120°50'05.5" E.
Lat. 24°43'12.0" N., Long. 120°48'46.9" E.
Lat. 24°41'58.2" N., Long. 120°49'35.9" E.
Lat. 24°41'35.8" N., Long. 120°49'01.5" E.
Lat. 24°41'27.6" N., Long. 120°48'24.1" E. *WGS84

Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung