交通部航港局航船布告

中華民國 115 年 2 月 5 日

62　凝航公告(北區)緊急搶修台馬第二海纜淡水至東引段斷線障礙作業。

依　　據　內政部 115 年 2 月 5 日台內地字第 1150105496 號函

說　　明　一、時間：115 年 2 月 4 日起至 115 年 4 月 30 日止。

二、地點：

(一) 距淡水沙崙機房約 162 公里

(二) 距淡水沙崙機房約 117 公里

三、作業船舶：「 Cable Retriever 」

四、中華電信股份有限公司網路技術分公司於維護之台馬第二海纜淡水至東引段於 114 年 10 月 28 日及 12 月 3 日發生斷線障礙，擬自 115 年 2 月 4 日起至 115 年 4 月底前往下列位址連線範圍內進行海纜故障緊急搶修作業，請非旨述計畫相關之工作船舶行經該水域時注意避讓，以確保航行安全。

位　　置　北緯 26°20'33.0" ，東經 120°44'55.2" 。
北緯 26°19'54.0" ，東經 120°45'50.4" 。
北緯 26°06'42.0" ，東經 121°04'23.4" 。
北緯 26°05'59.4" ，東經 121°05'22.2" 。 *WGS84

交通部航港局
局長　葉協隆

NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

February 5, 2026

62 Taiwan Northern Waters ─ Submarine Cable Maintenance

Source Ministry Of The Interior, Letter No. 1150105496 dated February 5, 2026.

Details Submarine cable maintenance workwithin area bounded by thefollowingposition will be undertaken by □Cable Retriever□ from December23 ,2025 to April 30 , 2026.Mariners are advised to navigate with cautionin this area.

Positions Lat. 26°20'33.0" N., Long. 120°44'55.2" E.
Lat. 26°19'54.0" N., Long. 120°45'50.4" E.
Lat. 26°06'42.0" N., Long. 121°04'23.4" E.
Lat. 26°05'59.4" N., Long. 121°05'22.2" E. *WGS84

Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung