



交通部航港局航船布告

中華民國 112 年 2 月 3 日

45 礙航公告(南區)台灣中油股份有限公司天然氣事業部永安液化天然氣廠「永安廠港區及航道水深改善工程」之需要，於浚挖區編號B2、B2a、B3、B4、B5浮燈標遷移作業之航船布告案

依據 台灣中油股份有限公司天然氣事業部永安液化天然氣廠 112 年 2 月 3 日永安港務發字第 11210077710 號函

說明 一、目前浮燈標編號及位置

B2 北緯 22°49' 43.0" ，東經 120°11' 23.0" 。

B2a 北緯 22°49' 15.0" ，東經 120°11' 42.0" 。

B3 北緯 22°49' 03.0" ，東經 120°11' 59.0" 。

B4 北緯 22°49' 08.0" ，東經 120°11' 30.0" 。

B5 北緯 22°48' 49.3" ，東經 120°11' 28.0" 。

遷移後新位置

B2 北緯 22°49' 43.0" ，東經 120°11' 29.0" 。

B2a 北緯 22°49' 15.0" ，東經 120°11' 49.0" 。

B3 北緯 22°49' 02.0" ，東經 120°12' 00.0" 。

B4 北緯 22°49' 08.0" ，東經 120°11' 26.0" 。

B5 北緯 22°48' 49.0" ，東經 120°11' 26.0" 。

二、請船舶注意避讓及瞭望，以維航行安全。

位置 北緯 22°49'43.0" ，東經 120°11'29.0" 。

北緯 22°49'15.0" ，東經 120°11'49.0" 。

北緯 22°49'02.0" ，東經 120°12'00.0" 。

北緯 22°49'08.0" ，東經 120°11'26.0" 。

北緯 22°48'49.0" ，東經 120°11'26.0" 。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

February 3, 2023

- 45** Yong An LNG port dredging work- light buoys relocation notice
- Source CPC Corporation, Taiwan Yung An receiving terminal letter No. 11210077710
February 3, 2023.
- Details Light buoy information has been updated. See attachment and Mariners are advised to navigate with caution in this area.
- Positions Lat. 22°49'43.0" N., Long. 120°11'29.0" E.
Lat. 22°49'15.0" N., Long. 120°11'49.0" E.
Lat. 22°49'02.0" N., Long. 120°12'00.0" E.
Lat. 22°49'08.0" N., Long. 120°11'26.0" E.
Lat. 22°48'49.0" N., Long. 120°11'26.0" E. *WGS84

*Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung*