



交通部航港局航船布告

中華民國 115 年 4 月 7 日

187 礙航公告(中區)(至115年12月31日)海龍二號、海龍三號風電股份有限公司進行海纜調查作業

依據 依據海龍二號風電股份有限公司 115 年 4 月 1 日海二電字第 2026040101 號函及海龍三號風電股份有限公司 115 年 4 月 1 日海三電字第 2026040101 號函辦理

說明 一、依據海龍二號風電股份有限公司 115 年 4 月 1 日海二電字第 2026040101 號函及海龍三號風電股份有限公司 115 年 4 月 1 日海三電字第 2026040101 號函辦理。

二、海龍二、三號風電股份有限公司委託樹木旺再生能源有限公司執行輸出海纜調查，作業期間自 2026 年 4 月 8 日至 2026 年 12 月 31 日，相關資訊詳附件所示，請周邊作業船隻注意避讓。

位 置 北緯 24°01'49.3" ，東經 119°40'34.8" 。
北緯 24°02'33.2" ，東經 119°40'53.3" 。
北緯 24°02'40.1" ，東經 119°55'40.0" 。
北緯 23°57'01.5" ，東經 119°51'18.7" 。
北緯 24°06'59.4" ，東經 120°23'47.2" 。
北緯 24°07'12.2" ，東經 120°22'47.5" 。
北緯 24°07'14.4" ，東經 120°20'35.7" 。
北緯 24°07'48.0" ，東經 120°18'01.7" 。
北緯 24°07'48.6" ，東經 120°17'58.5" 。
北緯 24°07'50.0" ，東經 120°17'55.8" 。
北緯 24°08'02.3" ，東經 120°16'46.3" 。
北緯 24°08'02.8" ，東經 120°16'38.5" 。
北緯 24°08'01.6" ，東經 120°16'12.4" 。
北緯 24°08'01.0" ，東經 120°16'01.6" 。
北緯 24°07'47.7" ，東經 120°10'48.7" 。
北緯 24°08'07.6" ，東經 120°10'18.7" 。
北緯 24°02'44.2" ，東經 119°55'51.1" 。
北緯 24°02'44.2" ，東經 119°55'43.4" 。
北緯 24°02'04.3" ，東經 119°55'12.3" 。
北緯 24°02'11.8" ，東經 119°55'58.1" 。
北緯 24°07'30.7" ，東經 120°10'13.8" 。
北緯 24°07'14.5" ，東經 120°10'38.2" 。
北緯 24°07'35.9" ，東經 120°16'36.1" 。
北緯 24°07'42.0" ，東經 120°16'42.0" 。
北緯 24°07'30.0" ，東經 120°17'48.0" 。
北緯 24°07'26.7" ，東經 120°17'53.3" 。
北緯 24°06'56.9" ，東經 120°20'27.9" 。
北緯 24°06'54.7" ，東經 120°22'46.5" 。
北緯 24°06'42.8" ，東經 120°23'38.3" 。 *WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

April 7, 2026

- 187** Changhua Taiwan Offshore-Hai Long 2, Hai Long 3 Offshore Wind Farm Ltd. to conduct an export cable survey
- Source Hai Long 2 Offshore Wind Power Co., Ltd, letter No. 2026040101 dated April 1, 2026.
Hai Long 3 Offshore Wind Power Co., Ltd, letter No. 2026040101 dated April 1, 2026.
- Details Hailong No. 2 and No. 3 Wind Power Co., Ltd. have commissioned Shumuwang Renewable Energy Co., Ltd. to conduct a survey of the submarine cable. The survey period is from April 8, 2026, to December 31, 2026. Relevant information is detailed in the attachment. Nearby vessels are advised to take precautions and avoid the area.
- Positions Lat. 24°01'49.3" N., Long. 119°40'34.8" E.
Lat. 24°02'33.2" N., Long. 119°40'53.3" E.
Lat. 24°02'40.1" N., Long. 119°55'40.0" E.
Lat. 23°57'01.5" N., Long. 119°51'18.7" E.
Lat. 24°06'59.4" N., Long. 120°23'47.2" E.
Lat. 24°07'12.2" N., Long. 120°22'47.5" E.
Lat. 24°07'14.4" N., Long. 120°20'35.7" E.
Lat. 24°07'48.0" N., Long. 120°18'01.7" E.
Lat. 24°07'48.6" N., Long. 120°17'58.5" E.
Lat. 24°07'50.0" N., Long. 120°17'55.8" E.
Lat. 24°08'02.3" N., Long. 120°16'46.3" E.
Lat. 24°08'02.8" N., Long. 120°16'38.5" E.
Lat. 24°08'01.6" N., Long. 120°16'12.4" E.
Lat. 24°08'01.0" N., Long. 120°16'01.6" E.
Lat. 24°07'47.7" N., Long. 120°10'48.7" E.
Lat. 24°08'07.6" N., Long. 120°10'18.7" E.
Lat. 24°02'44.2" N., Long. 119°55'51.1" E.
Lat. 24°02'44.2" N., Long. 119°55'43.4" E.
Lat. 24°02'04.3" N., Long. 119°55'12.3" E.
Lat. 24°02'11.8" N., Long. 119°55'58.1" E.
Lat. 24°07'30.7" N., Long. 120°10'13.8" E.
Lat. 24°07'14.5" N., Long. 120°10'38.2" E.
Lat. 24°07'35.9" N., Long. 120°16'36.1" E.
Lat. 24°07'42.0" N., Long. 120°16'42.0" E.
Lat. 24°07'30.0" N., Long. 120°17'48.0" E.
Lat. 24°07'26.7" N., Long. 120°17'53.3" E.
Lat. 24°06'56.9" N., Long. 120°20'27.9" E.
Lat. 24°06'54.7" N., Long. 120°22'46.5" E.
Lat. 24°06'42.8" N., Long. 120°23'38.3" E. *WGS84

*Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC*

