



交通部航港局航船布告

中華民國 112 年 3 月 21 日

135

礙航公告(中南區)(展延至112年6月30日)台灣中油股份有限公司所送「永安至通霄第二條海底輸氣管線興建計畫」勘測作業區域圖、作業時間表、作業船舶等資料

依
說

據
明

內政部 112 年 3 月 17 日台內地字第 1120109852 號函。

一、作業時間:原定民國 111 年 12 月 12 日至 112 年 3 月 31 日,展延至 112 年 6 月 30 日。

二、作業船舶:寶拉麗絲號、寶拉麗絲 3 號。

三、作業區域:請參閱附件。

四、航行船隻請注意瞭望及避讓,以策安全。

位

置

北緯 23°54'17.9", 東經 120°01'24.2"。

北緯 23°58'23.2", 東經 120°03'50.2"。

北緯 24°03'14.3", 東經 120°07'38.2"。

北緯 24°04'24.8", 東經 120°08'33.0"。

北緯 24°07'31.8", 東經 120°11'00.2"。

北緯 24°09'13.8", 東經 120°12'24.0"。

北緯 24°10'51.3", 東經 120°13'44.7"。

北緯 24°13'26.0", 東經 120°15'53.2"。

北緯 24°20'30.8", 東經 120°21'34.7"。

北緯 24°23'06.0", 東經 120°23'37.9"。

北緯 24°25'05.3", 東經 120°26'42.5"。

北緯 24°26'47.1", 東經 120°29'17.5"。

北緯 24°29'35.3", 東經 120°33'55.7"。

北緯 24°29'44.5", 東經 120°35'54.4"。

北緯 24°29'32.9", 東經 120°36'27.5"。

北緯 24°29'01.7", 東經 120°37'29.4"。

北緯 24°28'55.1", 東經 120°38'04.1"。

北緯 24°28'54.5", 東經 120°38'24.0"。*WGS84

海

圖

普通海圖第 0001, 00011, 0001A(四), 00051, 00013, 00014, 0307, 0312, 0313, 0328B, 0336, 0338, 0340, 04505, 0471, 0479, 04506, 00041, 04507, 0356, 0001A(二), 0106, 0328A, 04508, 04509, 04510, 0361 號。

電子海圖第 1U320220, 1U320230, 1U319230, 1U320240, 1U420221, 1U420230, 1U419232, 1U419233, 1U420231, 1U420240, 1U420242, 1U50339A 號。

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

March 21, 2023

135 Taiwan West Water-CPC Corporation Subsea Pipeline Installation Postponed

Source	Ministry of the Interior, letter No.1120109852 dated March 17, 2023.
Details	The completed date of the maritime work is postponed to 30th June, 2023. Marine rs are advised to navigate with caution in the area.
Positions	Lat. 23°54'17.9" N., Long. 120°01'24.2" E. Lat. 23°58'23.2" N., Long. 120°03'50.2" E. Lat. 24°03'14.3" N., Long. 120°07'38.2" E. Lat. 24°04'24.8" N., Long. 120°08'33.0" E. Lat. 24°07'31.8" N., Long. 120°11'00.2" E. Lat. 24°09'13.8" N., Long. 120°12'24.0" E. Lat. 24°10'51.3" N., Long. 120°13'44.7" E. Lat. 24°13'26.0" N., Long. 120°15'53.2" E. Lat. 24°20'30.8" N., Long. 120°21'34.7" E. Lat. 24°23'06.0" N., Long. 120°23'37.9" E. Lat. 24°25'05.3" N., Long. 120°26'42.5" E. Lat. 24°26'47.1" N., Long. 120°29'17.5" E. Lat. 24°29'35.3" N., Long. 120°33'55.7" E. Lat. 24°29'44.5" N., Long. 120°35'54.4" E. Lat. 24°29'32.9" N., Long. 120°36'27.5" E. Lat. 24°29'01.7" N., Long. 120°37'29.4" E. Lat. 24°28'55.1" N., Long. 120°38'04.1" E. Lat. 24°28'54.5" N., Long. 120°38'24.0" E. *WGS84
Chart affected	NMOO Charts 0001, 00011, 0001A(四), 00051, 00013, 00014, 0307, 0312, 0313, 0328B, 0336, 0338, 0340, 04505, 0471, 0479, 04506, 00041, 04507, 0356, 0001A(二), 0106, 0328A, 04508, 04509, 04510, 0361. ENC 1U320220, 1U320230, 1U319230, 1U320240, 1U420221, 1U420230, 1U419232, 1U419233, 1U420231, 1U420240, 1U420242, 1U50339A.

*Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung*