



## 交通部航港局航船布告

中華民國 115 年 3 月 24 日

### 166 礙航公告(中區)(至119年10月18日)彰芳暨西島離岸風場之風場維護更新船舶資訊

依據 彰芳風力發電股份有限公司 115 年 3 月 23 日彰芳風力字第 1150323001 號  
說明 1. 旨述風場維護工作作業期間自 2026 年 4 月 1 日至 2030 年 10 月 18 日，新增船舶東方探勘者 (Orient Explorer) 執行風場運維工作。

2. 非旨述計畫相關之工作船隻請避開該區域，注意航行以策安全，相關資料詳如附件。

位置 北緯 24°02'14.3"，東經 120°07'02.0"。  
北緯 24°02'21.3"，東經 120°09'13.5"。  
北緯 24°02'18.0"，東經 120°11'31.5"。  
北緯 23°59'52.2"，東經 120°10'46.2"。  
北緯 23°58'00.5"，東經 120°08'24.6"。  
北緯 23°58'14.4"，東經 120°05'06.5"。  
北緯 24°00'09.6"，東經 120°05'25.4"。  
北緯 23°58'01.5"，東經 120°12'04.2"。  
北緯 23°56'49.3"，東經 120°10'57.3"。\*WGS84

交通部航港局局長  
葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

March 24, 2026

**166**

Chang Fang Wind Power Co Update maintenance activity ship information

Source

Chang Fang Wind Power Co. No.1150323001 dated March 23, 2026.

Details

1. The wind farm maintenance work will be conducted from April 1, 2026 to October 18, 2030, with the addition of the vessels Orient Explorer to perform wind farm operation and maintenance work.

2. Vessels not involved in the planned work should avoid this area and exercise caution when navigating. Details are attached.

Positions

Lat. 24°02'14.3" N., Long. 120°07'02.0" E.

Lat. 24°02'21.3" N., Long. 120°09'13.5" E.

Lat. 24°02'18.0" N., Long. 120°11'31.5" E.

Lat. 23°59'52.2" N., Long. 120°10'46.2" E.

Lat. 23°58'00.5" N., Long. 120°08'24.6" E.

Lat. 23°58'14.4" N., Long. 120°05'06.5" E.

Lat. 24°00'09.6" N., Long. 120°05'25.4" E.

Lat. 23°58'01.5" N., Long. 120°12'04.2" E.

Lat. 23°56'49.3" N., Long. 120°10'57.3" E. \*WGS84

*Director General Hsieh-Lung, Yeh  
Maritime and Port Bureau, MOTC*